


Pressure ranges 0 – 100 mbar to 0 – 1000 bar

9810
09/15



PTM



Dimensional Data (mm) and Weights (kg)					
Model	Variant	l (mm)	a (mm)	b (mm)	approx. weight
PTM	up to 0 – 100 bar	88 (93)	20	10	0.21 kg
	> 0 – 160 bar	97 (102)	20	19	0.23 kg

The values in brackets are for the output signals 0...20 mA

Wiring Diagram



Please note:
Wiring diagram for version with circular plug connector
M 12x1 see supplied operating instructions!