


TEDELFT

ADAPTERS AND CROSS-OVERS



High Pressure to Medium Pressure

A	→	Size	1/16	1/8	1/4	3/8	1/2
B	↓	Type	HP	HP	HP	HP	HP
Size	Type						
1/16	MP		C-1211	C-2211	C-3211	C-4211	C-5211
1/8	MP		C-1221	C-2221	C-3221	C-4221	C-5221
1/4	MP		C-1231	C-2231	C-3231	C-4231	C-5231
3/8	MP		C-1241	C-2241	C-3241	C-4241	C-5241
1/2	MP		C-1261	C-2261	C-3261	C-4261	C-5261

Medium Pressure to High Pressure

A	→	Size	1/16	1/8	1/4	3/8	1/2
B	↓	Type	MP	MP	MP	MP	MP
Size	Type						
1/16	HP		C-1212	C-2112	C-3112	C-4112	C-5112
1/8	HP		C-1122	C-2122	C-3122	C-4122	C-5122
1/4	HP		C-1132	C-2132	C-3132	C-4132	C-5132
3/8	HP		C-1142	C-2142	C-3142	C-4142	C-5142
1/2	HP		C-1162	C-2162	C-3162	C-4162	C-5162

KEY:

TW = Twin Ferrule Type
 LV = Laboratory Valve Type
 MP = Medium Pressure Type
 HP = High Pressure Type

*Can't find what you need?
 Then call 01296 431804*